

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 22-02559 Inspection Number: 03812325

Building Inspection Report

Code Reviewed Under: 2018 IBC

Permit Information

Job Address: 565A FLINTWOOD RD FRANKTOWN Job Type: Building Description: CM - Cell Site Scope of Work: Alteration

Inspection Details

Inspection Date: 06/08/2023 Inspection Time: 10:58 AM Inspection Type: Electric Service Equipment Inspection Code: 23 Meter Release: Provider: CORE Outcome: Disapproved Inspected By: Justin Lett Charge Reinspection Fee: No

Comments

1. Listed add-a-lugs required at neutral bar in fused disconnect 2. Provide accurate fault current value-per CORE, fault current at transformer is 6944 3. Arc flash labels required 4. Completely backfill trench adjacent to transformer 5. Signs required per 702.7(A), (B), (C)-can do these signs at final