



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglasco.gov

Permit Number: 26-02997
Inspection Number: 04020704

Building Inspection Report

Permit Information

Job Address: 7179 LEOPARD GATE LITTLETON
Job Type: Mechanical
Description: Furnace/AC Combo (Primary Residence)

Inspection Details

Inspection Date: 04/16/2026
Inspection Time: 11:03 AM
Inspection Type: Final HVAC
Inspection Code: 39
Outcome: Disapproved
Inspected By: Brent Althouse
Charge Reinspection Fee: No

Comments

1. CO detector not installed in basement.
2. Heat pump is installed on earth, decaying landscaping and gravel.