

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 13-02362 Inspection Number: 03035326

Building Inspection Report

Code Reviewed Under: 2012 IRC

Permit Information

Job Address: 5044 VERMILLION DR CASTLE ROCK Job Type: Building Description: RS - Stock Scope of Work: New

Inspection Details

Inspection Date: 07/11/2013 Inspection Time: 12:00 AM Inspection Type: Exterior Wall Sheathing Inspection Code: 104 Outcome: Approved Inspected By: Kerry Keller Charge Reinspection Fee: No