

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497

Email: dcbuilding@douglas.co.us

Permit Number: 13-02362 Inspection Number: 03057456

Building Inspection Report

Code Reviewed Under: 2012 IRC

Permit Information

Job Address: 5044 VERMILLION DR CASTLE ROCK

Job Type: Building
Description: RS - Stock
Scope of Work: New

Inspection Details

Inspection Date: 11/08/2013 Inspection Time: 12:00 AM Inspection Type: Final Electric

Inspection Code: 42
Outcome: Disapproved
Inspected By: Rich Edgett
Charge Reinspection Fee: No

Comments

- 1) Fire Dept approval required
- 2) A/C unit incomplete
- 3) Panel index incomplete

NO INSPECTION