



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglasco.gov

Permit Number: 13-06695
Inspection Number: 03080712

Building Inspection Report

Code Reviewed Under: 2012 IRC

Permit Information

Job Address: 5043 VERMILLION DR CASTLE ROCK
Job Type: Building
Description: RS - Stock
Scope of Work: New

Inspection Details

Inspection Date: 04/03/2014
Inspection Time: 12:00 AM
Inspection Type: Final Electric
Inspection Code: 42
Outcome: Disapproved
Inspected By: Rich Edgett
Charge Reinspection Fee: No

Comments

- 1) Center cabinet missing btwn mstr bath sinks
- 2) Frpl incomplete
- 3) Study floor boxes not flush to surface
- 4) Stap flex @ sump
- 5) Power strip not permitted @ security panels
- 6) Bond Intellinet box per mfrs specs
- 7) Check rear grade level recept (snow)