

Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 17-13326
Inspection Number: 03391871

Building Inspection Report

Code Reviewed Under: 2012 IRC

Permit Information

Job Address: 10036 COPENHAGEN ST PARKER
Job Type: Building
Description: RS - Basement
Scope of Work: Alteration

Inspection Details

Inspection Date: 02/21/2018
Inspection Time: 12:00 AM
Inspection Type: Rough Electric
Inspection Code: 22
Outcome: Disapproved
Inspected By: Rich Edgett
Charge Reinspection Fee: No

Comments

- 1) EGCs in 3-gang at bottom of stairs not spliced together
- 2) 2nd bath fan incomplete
- 3) 30"W workspace required in front of subpanel
- 4) Bushing required on SER connector in subpanel
- 5) Recess cans in E bdrm closet must be 6" horiz from side wall shelf space
- 6) NM not permitted in conduit in slab on grade
- 7) 2 14-2 cables not permitted in pan box over island
- 8) Permanent access required to UFER
- 9) Max OCPD for #2 Al SER is 90A (Not a main feeder)