

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497

Email: dcbuilding@douglas.co.us

Permit Number: 18-05119 Inspection Number: 03430673

Building Inspection Report

Permit Information

Job Address: 9166 CORRAL LN CASTLE ROCK

Job Type: Mechanical

Description: Air Conditioner (Primary Residence)

Inspection Details

Inspection Date: 08/16/2018 Inspection Time: 12:00 AM Inspection Type: Final HVAC

Inspection Code: 39
Outcome: Disapproved
Inspected By: Matt Mazzara
Charge Reinspection Fee: No

Comments

1)List elec contractor on permit 2)Saddle valve not allowed humidifier

3)AC GFCI to be WR type 4)Label AC GFCI breaker