

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 18-05119 Inspection Number: 03431200

Building Inspection Report

Permit Information

Job Address: 9166 CORRAL LN CASTLE ROCK Job Type: Mechanical Description: Air Conditioner (Primary Residence)

Inspection Details

Inspection Date: 08/17/2018 Inspection Time: 7:50 AM Inspection Type: Final Electric Inspection Code: 42 Outcome: Disapproved Inspected By: Matt Mazzara Charge Reinspection Fee: No

Comments

See HVAC