

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 18-05368 Inspection Number: 03449528

Building Inspection Report

Permit Information

Job Address: 3823 CASTLE BUTTE DR CASTLE ROCK Job Type: Mechanical Description: Air Conditioner (Primary Residence)

Inspection Details

Inspection Date: 11/19/2018 Inspection Time: 12:00 AM Inspection Type: Final Electric Inspection Code: 42 Outcome: Disapproved Inspected By: Rick Sugar Charge Reinspection Fee: No

Comments

EGC must terminate on the EGC terminal bar in the subpanel, send email photo to approve