



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglasco.gov

Permit Number: 19-13314
Inspection Number: 03527781

Building Inspection Report

Code Reviewed Under: 2012 IRC

Permit Information

Job Address: 861 SWANDYKE DR CASTLE ROCK
Job Type: Building
Description: RS - Basement
Scope of Work: Alteration

Inspection Details

Inspection Date: 12/13/2019
Inspection Time: 12:00 AM
Inspection Type: Rough Electric
Inspection Code: 22
Outcome: Disapproved
Inspected By: Rick Sugar
Charge Reinspection Fee: No

Comments

Per Douglas county amendments 10 openings on a 15 amp circuit
NEED to list a electrical contractor
Outlet required left of the fireplace and allow 11/4" NM to face of the stud
Box fill exceeded right of the wet bar sink
Ok to sheet rock
Check HR terminations
ARC fault throughout , except North exterior wall