**Douglas County Building Division**
**100 Third Street STE #20**
**Castle Rock, CO 80104**
**Phone: 303.660.7497**
**Email: dcbuilding@douglasco.gov**

**Permit Number:** 19-13073
**Inspection Number:** 03531140

# Building Inspection Report

**Code Reviewed Under:** 2012 IRC

## Permit Information

**Job Address:** 11200 SWEET CICELY LN PARKER
**Job Type:** Building
**Description:** RS - Basement
**Scope of Work:** Alteration

## Inspection Details

**Inspection Date:** 01/06/2020
**Inspection Time:** 12:00 AM
**Inspection Type:** Rough Electric
**Inspection Code:** 22
**Outcome:** Disapproved
**Inspected By:** Henry VanSchaack
**Charge Reinspection Fee:** No

## Comments

1) fireplace incomplete; 2) max 4 cables per stack-it bundled over 24"; 3) max 2 cables per 1/2" connector in sub-panel; 4) max 10 openings per 15a ckt, lighting exceeds; 5) completely remove bond screw from sub-panel