



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 19-13682
Inspection Number: 03553756

Building Inspection Report

Code Reviewed Under: 2012 IRC

Permit Information

Job Address: 3464 CASTLE BUTTE DR CASTLE ROCK
Job Type: Building
Description: RS - Residential
Scope of Work: Alteration

Inspection Details

Inspection Date: 05/11/2020
Inspection Time: 12:00 AM
Inspection Type: Final Electric
Inspection Code: 42
Outcome: Disapproved
Inspected By: Rick Sugar
Charge Reinspection Fee: No

Comments

Exercise room has a garage door and garage must be fire rated
20 amp required for the outlet in the pantry
FMC required for the master bedroom in floor control wire
Outlet required right of the 2nd NE bedroom door
Note; need to inspect rec room fireplace terminations
Pendant light cannot be less than 3' from masters tub