Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglasco.gov

Permit Number: 20-03866
Inspection Number: 03557277

Building Inspection Report

Permit Information

Job Address: 7781 N SUNRISE TRL PARKER
Job Type: Mechanical
Description: Furnace/AC Combo (Primary Residence)

Inspection Details

Inspection Date: 05/29/2020
Inspection Time: 12:00 AM
Inspection Type: Final Electric
Inspection Code: 42
Outcome: Disapproved
Inspected By: Justin Lett
Charge Reinspection Fee: No

Comments

1. Disc clearance at west A/C 2. 40A breaker in GE panel required to be Classified or GE 3. Furnace disconnects required to be below 6’7” 4. CO alarms outside bedroom entrances w/in 15’ throughout 5. Label furnace breakers and furnace disconnects to match.