



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 21-06510

Inspection Number: 03643318

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 5394 SEDONA DR PARKER

Job Type: Building

Description: RS - Basement

Scope of Work: Alteration

Inspection Details

Inspection Date: 08/06/2021

Inspection Time: 1:46 PM

Inspection Type: Final Electric

Inspection Code: 42

Outcome: Disapproved

Inspected By: Henry VanSchaack

Charge Reinspection Fee: No

Comments

Twin breaker installed to make room for AFCI is not permitted in this breaker space and is not making good electrical contact, must be moved to a correct bus space or panel may need to be replaced