**Douglas County Building Division**
**100 Third Street STE #20**
**Castle Rock, CO 80104**
**Phone: 303.660.7497**
**Email: dcbuilding@douglasco.gov**

**Permit Number:** 21-00698
**Inspection Number:** 03645792

# Building Inspection Report

**Code Reviewed Under:** 2018 IRC

## Permit Information

**Job Address:** 5771 DISTANT VIEW PL PARKER
**Job Type:** Building
**Description:** RS - Custom
**Scope of Work:** New

## Inspection Details

**Inspection Date:** 08/18/2021
**Inspection Time:** 1:40 PM
**Inspection Type:** Interior Gas Line
**Inspection Code:** 30
**Meter Release:**
**Provider:** Xcel
**Outcome:** Disapproved
**Inspected By:** Richard Miller
**Charge Reinspection Fee:** No

## Comments

1. Flex connectors not listed for concealed spaces at basement fireplace
2. Gas line needs to be piped into fire box of fireplace
3. Retest system