

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497

Email: dcbuilding@douglas.co.us

Permit Number: 21-00698 Inspection Number: 03645792

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 5771 DISTANT VIEW PL PARKER

Job Type: Building
Description: RS - Custom
Scope of Work: New

Inspection Details

Inspection Date: 08/18/2021 **Inspection Time:** 1:40 PM

Inspection Type: Interior Gas Line

Inspection Code: 30 Meter Release: Provider: Xcel

Outcome: Disapproved Inspected By: Richard Miller Charge Reinspection Fee: No

Comments

- 1. Flex connectors not listed for concealed spaces at basement fireplace
- 2. Gas line needs to be piped into fire box of fireplace
- 3. Retest system