



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 21-08959

Inspection Number: 03688668

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 5394 SEDONA DR PARKER

Job Type: Building

Description: RS - Basement

Scope of Work: Alteration

Inspection Details

Inspection Date: 02/24/2022

Inspection Time: 10:29 AM

Inspection Type: Final Electric

Inspection Code: 42

Outcome: Disapproved

Inspected By: Thomas Buzo

Charge Reinspection Fee: No

Comments

7) Protect horizontal runs of NM cable in unfinished area of basement. 9) GFCI protection req for receptacles within 6' of wet bar sink. 12) terminate unused ends of service into boxes, (Can not leave ends hanging in crawl spaces) 110.14 15) AFCI protection require for receptacles at bottom of stairs. 210.12

Note: Hot tub disconnected at time of inspection.

Service remained unchanged.