



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 21-05022
Inspection Number: 03709569

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 8061 PARADISO CT LITTLETON
Job Type: Building
Description: RS - Custom
Scope of Work: New

Inspection Details

Inspection Date: 05/19/2022
Inspection Time: 4:40 PM
Inspection Type: Rough Electric
Inspection Code: 22
Outcome: Disapproved
Inspected By: Rick Sugar
Charge Reinspection Fee: No

Comments

- 1) DC amendments 10 on a 15 amp circuits, 12 on a 20 , 4 on small appliance circuits
- 2) Allows clearance at the AC disconnects
- 3) Exterior PP boxes exceeded box fill
- 4) Outlet required at the center garage bay
- 5) No more than 4 NM cables per stack throughout
- 6) Dedicated circuits required for the elevator space lighting , machine room and equipment lighting
- 7) KO filler at study PP box in the study
- 8) Great room fan box not installed
- 9) Staircase ceiling box not bonded
- 10) Running boards at attic accesses
- 11) Inspection terminated need to inspect basement ,rear grade and decks