



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 21-05022
Inspection Number: 03713219

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 8061 PARADISO CT LITTLETON
Job Type: Building
Description: RS - Custom
Scope of Work: New

Inspection Details

Inspection Date: 06/01/2022
Inspection Time: 10:28 AM
Inspection Type: Rough Electric
Inspection Code: 22
Outcome: Disapproved
Inspected By: Jeremy Bock
Charge Reinspection Fee: No

Comments

1. Bond coach light at garage-east coach light
2. Box fill exceeded at porch pan at patio-master bedroom
3. Add light at under stair closet-bottom of basement stairs
4. Furnace wiring incomplete
5. Secure cables within 12" of panel in furnace room
6. Mechanically bond EGCs at light box in furnace room
7. 6' / 12' rule at finished storage room
8. Install fan box at exercise room
9. Install basement patio light cables in listed boxes
10. Outlet required within 6 ft of fixed glass at basement patio doorway
11. Install outlet box at basement fireplace-install dedicated circuit