



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 21-05022
Inspection Number: 03716411

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 8061 PARADISO CT LITTLETON
Job Type: Building
Description: RS - Custom
Scope of Work: New

Inspection Details

Inspection Date: 06/14/2022
Inspection Time: 3:39 PM
Inspection Type: Electric Service Equipment
Inspection Code: 23
Meter Release:
Provider: CORE
Outcome: Disapproved
Inspected By: Matt Mazzara
Charge Reinspection Fee: No

Comments

1)disconnect CM and seal KO
2)complete feeder terminations and install breakers pedestal
3)cold water pipe GEC req
4)inter system bond req at disconnect (can check at final)
5)label pedestal, disconnect and interior panel breakers 1,2 to match
UFER NE bsmt bed NW corner in ceiling
Note:bsmt electric FP 20amp circuit provided