



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 22-01302
Inspection Number: 03771413

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 3132 BELAY PT CASTLE ROCK
Job Type: Building
Description: RS - Stock
Scope of Work: New

Inspection Details

Inspection Date: 12/22/2022
Inspection Time: 11:48 AM
Inspection Type: Final Electric
Inspection Code: 42
Outcome: Disapproved
Inspected By: Thomas Buzo
Charge Reinspection Fee: No

Comments

- 1) Bathroom shower light shall be rated for a wet location. Bathroom by garage entry.
- 2) Grommet req where DW cord passes through cabinet.
- 3) Provide ladder to inspect wall oven disconnect.
- 4) Spark ring req - 2 gang switch box at kitchen back splash.
- 5) Level 2 Furnace Service receptacle SHALL be GFCI protected.
- 6) Re terminate sub panel feeders by final. Multiple strands damage. (noted at ESE inspection)
- 7) No power to exterior receptacles.
- 8) Next inspection check load connections and AFCI Protection through out house.