



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 23-00089
Inspection Number: 03796106

Building Inspection Report

Permit Information

Job Address: 9619 HUGGINS CT PARKER
Job Type: Mechanical
Description: Furnace/AC Combo (Primary Residence)

Inspection Details

Inspection Date: 04/03/2023
Inspection Time: 12:35 PM
Inspection Type: Final HVAC
Inspection Code: 39
Outcome: Approved
Inspected By: Justin Lett
Charge Reinspection Fee: No

Comments

Trim left side to gain full 1" of clearance to B-Vent. Owner on-site and is making correction. Correct and proceed.

Combustion air ok