

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 21-05022 Inspection Number: 03818128

Building Inspection Report

Code Reviewed Under: 2018 IRC

Permit Information

Job Address: 8061 PARADISO CT LITTLETON Job Type: Building Description: RS - Custom Scope of Work: New

Inspection Details

Inspection Date: 07/05/2023 Inspection Time: 11:07 AM Inspection Type: Final Electric Inspection Code: 42 Outcome: Disapproved Inspected By: Richard Perrone Charge Reinspection Fee: Yes

Comments

Not all corrections made: 2. Circuit directory inaccurate for panel below basement stairs - 408.4(A). 3. Breaker lock on (closed position) required for fire pump - 695.4(B)(3)(2). Re-inspection fee applied