

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497

Email: dcbuilding@douglas.co.us

Permit Number: 24-04592 Inspection Number: 03885459

Building Inspection Report

Permit Information

Job Address: 10631 RAMPART LN LITTLETON

Job Type: Mechanical

Description: Air Conditioner (Primary Residence)

Inspection Details

Inspection Date: 04/05/2024 Inspection Time: 10:38 AM Inspection Type: Final Electric

Inspection Code: 42 Outcome: Approved

Inspected By: Richard Perrone **Charge Reinspection Fee:** No