



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 24-04592
Inspection Number: 03885460

Building Inspection Report

Permit Information

Job Address: 10631 RAMPART LN LITTLETON
Job Type: Mechanical
Description: Air Conditioner (Primary Residence)

Inspection Details

Inspection Date: 04/05/2024
Inspection Time: 10:38 AM
Inspection Type: Air Conditioner
Inspection Code: 55
Outcome: Approved
Inspected By: Richard Perrone
Charge Reinspection Fee: No