



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 24-10666
Inspection Number: 03907630

Building Inspection Report

Permit Information

Job Address: 9351 SUMMIT RD PARKER
Job Type: Mechanical
Description: Furnace/AC Combo (Primary Residence)

Inspection Details

Inspection Date: 07/09/2024
Inspection Time: 3:03 PM
Inspection Type: Final HVAC
Inspection Code: 39
Outcome: Disapproved
Inspected By: Justin Lett
Charge Reinspection Fee: No

Comments

1. Vent terminations do not match installation instructions and distance to mechanical supply inlet of water heater not per requirements in installation manual 2. CO alarms required outside lower bedroom entrance within 15'