



Douglas County Building Division  
100 Third Street STE #20  
Castle Rock, CO 80104  
Phone: 303.660.7497  
Email: dcbuilding@douglas.co.us

Permit Number: 24-10666  
Inspection Number: 03907630

## Building Inspection Report

### Permit Information

**Job Address:** 9351 SUMMIT RD PARKER  
**Job Type:** Mechanical  
**Description:** Furnace/AC Combo (Primary Residence)

### Inspection Details

**Inspection Date:** 07/09/2024  
**Inspection Time:** 3:03 PM  
**Inspection Type:** Final HVAC  
**Inspection Code:** 39  
**Outcome:** Disapproved  
**Inspected By:** Justin Lett  
**Charge Reinspection Fee:** No

### Comments

1. Vent terminations do not match installation instructions and distance to mechanical supply inlet of water heater not per requirements in installation manual 2. CO alarms required outside lower bedroom entrance within 15'