

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 24-10666 Inspection Number: 03907783

Building Inspection Report

Permit Information

Job Address: 9351 SUMMIT RD PARKER Job Type: Mechanical Description: Furnace/AC Combo (Primary Residence)

Inspection Details

Inspection Date: 07/09/2024 Inspection Time: 3:02 PM Inspection Type: Air Conditioner Inspection Code: 55 Outcome: Disapproved Inspected By: Justin Lett Charge Reinspection Fee: No

Comments

Locking caps required at refrigerant ports