



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 24-10666
Inspection Number: 03907784

Building Inspection Report

Permit Information

Job Address: 9351 SUMMIT RD PARKER
Job Type: Mechanical
Description: Furnace/AC Combo (Primary Residence)

Inspection Details

Inspection Date: 07/09/2024
Inspection Time: 3:02 PM
Inspection Type: Final Electric
Inspection Code: 42
Outcome: Disapproved
Inspected By: Justin Lett
Charge Reinspection Fee: No

Comments

1. Water heater cannot be fed from furnace circuit 2. Secure EMT above furnace disc within 36"-358.30 3. Secure MC adjacent to furnace disc switch 4. A/C disconnect requires clearances per 110.26