



Douglas County Building Division
100 Third Street STE #20
Castle Rock, CO 80104
Phone: 303.660.7497
Email: dcbuilding@douglas.co.us

Permit Number: 24-12238

Inspection Number: 03920346

Building Inspection Report

Code Reviewed Under: 2021 IRC

Permit Information

Job Address: 10122 ATLANTA ST PARKER

Job Type: Building

Description: RS - Basement

Scope of Work: Alteration

Inspection Details

Inspection Date: 09/03/2024

Inspection Time: 12:13 PM

Inspection Type: Rough Electric

Inspection Code: 22

Outcome: Disapproved

Inspected By: Justin Lett

Charge Reinspection Fee: No

Comments

1. 300.4-recep in flat stud wall bottom of stairs, soffits 2. NPs at top plates where drywall was cut to fish down dry walled walls, above sub panel 3. Recep below 5'6" required in mech room 4. Flat NM cables not permitted to be stapled on edge 5. Secure sub feed SER at 4-1/2' intervals 6. Listed add-a-lugs required for subfeed neutral and EGC in main panel 7. Bond hard gas piping with #6 CU or equivalent upstream of yellow CSST fitting