

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 24-01909 Inspection Number: 03932576

Building Inspection Report

Code Reviewed Under: 2021 IRC

Permit Information

Job Address: 9900 SARA GULCH CIR PARKER Job Type: Building Description: RS - Custom Scope of Work: New

Inspection Details

Inspection Date: 10/25/2024 Inspection Time: 11:58 AM Inspection Type: Interior Gas Line Inspection Code: 30 Meter Release: Provider: Xcel Outcome: Disapproved Inspected By: Fredrick Mooney Charge Reinspection Fee: No

Comments

Need 10 psi test. Rough ok. Insulate at your own risk. Ok to insulate per electrical inspector.