

Douglas County Building Division 100 Third Street STE #20 Castle Rock, CO 80104 Phone: 303.660.7497 Email: dcbuilding@douglas.co.us

> Permit Number: 24-01909 Inspection Number: 03932577

Building Inspection Report

Code Reviewed Under: 2021 IRC

Permit Information

Job Address: 9900 SARA GULCH CIR PARKER Job Type: Building Description: RS - Custom Scope of Work: New

Inspection Details

Inspection Date: 10/25/2024 Inspection Time: 12:00 PM Inspection Type: Rough Frame Inspection Code: 29 Outcome: Disapproved Inspected By: Fredrick Mooney Charge Reinspection Fee: No

Comments

1. Np plumbing pipes in bathroom top plates.

2. Stud shoe ext wall x 6 at wet bar.

3. Therma guard at back of fireplace.

4. Draftstop fireplace stud bays or cap top chase to attic.

5. Attic vent required 1/300 sq ft.

Ok to insulate per electrical inspector.

Recall with insulation.