



Tri-County Health Department

Serving Adams, Arapahoe and Douglas Counties

Fiscal Control No. **4055**

USE PERMIT

For Existing Domestic and Non-Municipal
Sewage Disposal Systems

No record

This permit shall remain valid until the property is sold, otherwise altered from stated use, or until the sewage disposal system fails to operate in an approved manner.

Issued to David Gill

Address P.O. Box 442 Sedalia, CO 80135

Location of System: As above (1170 Madge Gulch - Sedalia)

Street Address

Legal Address Tract partly SW¹/₄, S5, & partly SE¹/₄, S6, T8S, R68W of 6th principle meridian

Date Feb. 3, 1987 Health Officer *John H. H. H. H.* Castle Rock Ofc.

The sewage disposal system, at the time of inspection, appeared to be in working order. The Department assumes no responsibility for the continued satisfactory operation of the sewage disposal system. If, at any time, the system malfunctions, action will be taken against the owner of record pursuant to the regulations of the Department and the statutes of the State of Colorado.

Permit Fee \$ 75.00 Check No. 2441 M.O. Cash Received by Ir Date 2/3/87
6.00 2442

If a bacteriological water test is required, please include a SEPARATE CHECK FOR \$6.00, payable to COLORADO DEPARTMENT OF HEALTH LABORATORIES.

TRI-COUNTY DISTRICT HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SERVICES

APPLICATION FOR USE PERMIT
FOR EXISTING DOMESTIC AND NON-MUNICIPAL SEWAGE DISPOSAL SYSTEMS

ADAMS CITY	AURORA	BRIGHTON	CASTLE ROCK	ENGLEWOOD
4301 E. 72nd Ave.	15400 E. 14th Pl.	22 S. 4th Ave.	355 S. Wilcox	4857 S. Broadway
288-6816	Suite 309	Suite 301	688-5145	761-1340
	341-9370	659-8333		

FORM MUST BE COMPLETED IN FULL

Name of Applicant David Gill Phone 773-7007 (o) 688-4162 H

Mailing Address of Applicant P.O. Box 442, Sedalia, Co. 80135
Permit to be Sent to:

Name Dave Gill, Box 442, Sedalia, Co. 80135

Address

Street Address & Complete Legal Description of Property for Which Permit is being Requested (Attach legal if necessary) A Tract in Partly SW Quarter of (1170 Madge Gutch - Sedalia) Section 5 and Partly in the SE 1/4 of Section 6 all in Township 8 South Range 68 West of the 6th Meridian, Douglas Co. Colorado

PROVIDE MAP OR DIRECTIONS FOR LOCATING PROPERTY ON REVERSE SIDE OF THIS APPLICATION.
Source of Water: ☒ Private Well ☐ Public (Specify) see note on back

Name of Original Home Owner (If Known) Bob & June Kuehne

Contractor who Installed System (If Known) ?

A non-refundable fee of \$75.00 shall be payable when the application is made. The permit issued as a result of this application shall remain valid until the property is sold or otherwise altered from domestic use or until the sewage disposal system fails to operate in an approved manner.

OWNER/AGENT CERTIFICATION

(I), David Gill (Kuehne orig. Bob - June owners)
dwelling at the location described in this application do hereby certify that the sewage disposal system has been in continuous use, operating satisfactorily, and without malfunction. The septic tank was pumped 3/84 (Date).
REGULATIONS REQUIRE SEPTIC TANKS BE PUMPED EVERY FOUR (4) YEARS.

DATE

February 3, 1987

SIGNATURE

[Signature]

Inspection Date 2-13-87


Approved ☒

Denied ☐


Public Health Sanitarian John Kiehn

Permit Fee \$ 75.00 Check No. 2441 M.O. 2442 Cash 6.00 Rec'd by ls Date 2/3/87

2-5-87 took Water Sample from green house. J. K.
 Not sure where septic is must notify owners!



S Take H₂O sample from Spicket from
 Inside Greenhouse



Tri-County Health Department

Serving Adams, Arapahoe and Douglas Counties

Hugh Rohrer, M.D., M.P.H.
Director

February 13, 1987

David Gill
P.O. Box 442
Sedalia, CO 80135

RE: Sec. 6, T8S, R68W, of the
6 PM - 1170 Madge Gultch

Dear Mr. Gill:

An inspection has been made, February 13, 1987, of the individual sewage disposal system located on the above referenced property.

There are no records available as to size and location of this system. At the time of the inspection the area pointed out to the inspector as the leachfield was covered with snow, therefore, a thorough assessment of the absorption field was impossible. What could be observed showed no apparent signs of malfunction at this time.

The well head meets the State Health Department standards.

Sincerely,

John Kleckner
Environmental Health Services

JK/lr

Enc. 1