

Tri-County Health Department

Serving Adams, Arapahoe and Douglas Counties

Fiscal Control No. 5440

USE PERMIT

For Existing Domestic and Non-Municipal
Sewage Disposal Systems

This permit shall remain valid until the property is sold, otherwise altered from stated use, or until the sewage disposal system fails to operate in an approved manner.

Issued to Robert McNeely

Address 10204 E. Meadow Run Parker, CO 80134

Location of System:
Street Address 10204 E. Meadow Run Parker, CO 80134

Legal Address Lot 138, Hidden Village #5 Douglas County

Date 7-29-87 Health Officer _____

The sewage disposal system, at the time of inspection, appeared to be in working order. The Department assumes no responsibility for the continued satisfactory operation of the sewage disposal system. If, at any time, the system malfunctions, action will be taken against the owner of record pursuant to the regulations of the Department and the statutes of the State of Colorado.

Permit Fee \$ 75.00 Check No. 1130 M.O. _____ Cash _____ Received by rb Date 7-29-87

TRI-COUNTY DISTRICT HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

2691

Adams City
4301 E. 72nd Ave.
288-6816

Brighton
1895 Egbert
659-4000

Englewood
4857 So. Broadway
761-1340

Aurora Office
15400 E. 14th Place
341-9370

Castle Rock
502 3rd St.
688-5145

West Adams City
7475 Dakin
428-8543

10204 E Meadow Run

APPLICATION FOR PERMIT TO CONSTRUCT, REMODEL, OR INSTALL A WASTE DISPOSAL SYSTEM

Address (Legal Description) Lot 138, Hidden Village, filing #5
 Owner Michael B. Parker Address 97 Maximus, Littleton Telephone No. 770-1214
 Installed by J.P. Spawley Address _____ Telephone No. _____

GENERAL INFORMATION

Type of Waste System: Residence X Commercial _____ Other _____
 Size of Lot 2.6 acres
 Percolation Rate #1 5.13 #2 6.0 #3 5.93 #4 _____ #5 _____ #6 _____
 Average 5.68 minutes per inch. Depth of 1st Ground Water None
 Soil Profile 1' to 10' See Attached Percolation Test #77319, AA Engineers & Assoc., Inc.
 Source of Domestic Water: Public (name) _____
 private well X Proposed _____ Depth _____ Distance from Sewage System _____
 Estimated Daily Sewage Flow 450 x 1.5 = 675 maximum G.P.D.

RESIDENCE

Number of Bedrooms 3 ⁴ Tubs or Showers 3 Toilets 3 Lavatory 3 Sinks 1

COMMERCIAL or Other: Attach estimated daily sewage flow data.
 Depth of Building Drain _____

CONSTRUCTION INFORMATION

Septic Tank Capacity 1250 2 compartment gallons Material Standard Concrete
 Inlet "1" or Baffle +3" Outlet Outlet "1" or Baffle -3" Inlet
 Soil Absorption System Trench _____ Bed X Pit _____
 Required Absorption Area in square feet 800 Filler Material Size 1/2" - 1 1/2" Depth 6"
 Distribution Line Material PVC perforated Diameter 4" Depth of Field = 3" minimum
5' maximum

or other type disposal system attach complete design and specification data.

Owner or Agent Michael B. Parker Date July 12, 1977

_____ Tri-County District H.D. _____ Date _____

_____ Water Pollution Control Comm. _____ Date _____

_____ Local Building & Zoning _____ Date _____

_____ Public Water & Sewer District _____ Date _____

Permit Issued M.L. Berglund (health officer) 7-13-77 Date _____

Supporting data (attached) _____ Soil Profile _____

Plot Plans _____ Special Design Data _____


Percolation Data _____

The construction of this nonmunicipal waste disposal system will comply with TCDHD Reg. #2/69 and all other applicable laws, ordinances, standards or resolutions. Michael B. Parker Owner.

System inspected and approved (date) 10-31-77 Sanitarian J. Julian

Permit File No. 2691 Fiscal Control No. 3864

Note: Search level is 30' from the dry creek





Tri-County Health Department Environmental Health Services

Application for Loan Inspection
For Existing Domestic and Non-Municipal Sewage Disposal Systems

FORM MUST BE COMPLETED IN FULL

Name of Applicant DEBBIE YOUNG Phone 841-5263

Mailing Address of Applicant P.O. BOX 1332

Name of Present Owner RONALD & SUSAN COOPER

Loan Inspection Report to be sent to: Name WATERFIELD FINANCIAL
m 6/20

Address PLAZA 6000 OFFICE PARK
6000 EVANS AVE BLD #2

City DENVER

State CO Zip 80222

Address and complete legal description of property -

10204 E. MEADOWRUN, PARKER COLORADO 80134

LOT 138 HIDDEN VILLAGE FILING 2

Bedrooms in Home 4 Year House was built 77

Source of Water: (Private Well) (Public (specify) _____)

Name of Original Homeowner (if known) _____

Is Residence (Occupied) (Vacant (specify how long) 1 day)

OWNER/AGENT CERTIFICATION

(I), DEBBIE YOUNG Owner (Owner) (Agent) (circle one) of the dwelling at the location described in this application do hereby certify that the sewage disposal system has been operating satisfactorily without malfunction. The septic tank was pumped and inspected on 3-13-89 (date).

6-16-89
Date

Deborah K. Young
Signature

A non-refundable fee of \$75.00 shall be payable to Tri-County Health Dept. when the application is made. If a bacteriological water test is required, please include a SEPARATE CHECK for \$6.00 payable to Colorado Department of Health Labs.

Check # 207 M.O. _____ Cash _____ Rec'd by De Date 6/16/89

TRI-COUNTY HEALTH DEPARTMENT
Loan Inspection Report Form

Property Address 10204 E Meadowrun

Legal Description Lot 138 Hidden Village #5

DEPARTMENTAL RECORD SEARCH: J. Angus Conducted By 6/16/89 Date

- (1) Record on File Yes () No
- (2) Original Permit # 2691
- (3) Date of Final Inspection: 10-31-77
- (4) Tank Size: 1250
- (5) Field Size: 925
- (6) # Bedrooms: 4 OR System Capacity: _____
- (7) Original Owner: MB Parker
- (8) Installer: JAK Exc.
- (9) Water Supply: well
- (10) Loan Inspections Issued: yes
Dates: 7/29/87
- (11) Repair Permits Issued: -
Dates: _____

SITE INSPECTION:

- (1) Properly Permitted: Yes () No
- (2) Soil Conditions at time of inspection: Dry () Wet () Snow Covered
- (3) Surfacing Sewage: () Yes No
- (4) Tank Tees/Baffles: See pumper report
- (5) # of Bedrooms in Home: 4 OR System Capacity _____
- (6) Properly sized based upon number of bedrooms OR system capacity
 Yes () No
- (7) Did TCHD representative take a water sample: () Yes No

COMMENTS Seach field showed no apparant evidence of malfunction at time of inspection. Well head location could not be found.

Neither Tri-County Health Department nor any of its agents or employees undertake or assume any liability to the owner of the above property, to any purchaser of the above property or to any lending agency making a loan on the above property in connection with either its examination of the property or in the report.

This inspection was conducted solely for the purpose of detecting health hazards observable at the time of inspection, and does not constitute a warranty that the system is without flaw or that it will continue to function in the future. Inspections requested during periods of rain, snow cover or when a residence is unoccupied may be of questionable value.

Date: 6-20-89 Signature John Bleckner
Environmental Health Specialist

DELBERT COUNTY SEPTIC SERVICE
 34565 Cimarron Trail
 ELIZABETH, COLORADO 80107
 688-2959 or 646-3326

SOLD BY		DATE 3-31-89	
NAME Country Pumps			
ADDRESS 210204 E. Meadow Run			
CASH	C.O.D.	CHARGE	ON ACCT.
		Pump Septic Tank	90 ⁰⁰
		Mileage	10 ⁰⁰
Total			100 ⁰⁰
RECEIVED BY			

T's ok

3076

Thank You

All claims and returned goods MUST be accompanied by this bill.

If a bacteriological water test is required, please include a SEPARATE CHECK FOR \$6.00, payable to COLORADO DEPARTMENT OF HEALTH LABORATORIES.

TRI-COUNTY DISTRICT HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SERVICES

5490

APPLICATION FOR USE PERMIT
FOR EXISTING DOMESTIC AND NON-MUNICIPAL SEWAGE DISPOSAL SYSTEMS

ADAMS CITY 4301 E. 72nd Ave. 288-6816	AURORA 15400 E. 14th Pl. Suite 309 341-9370	BRIGHTON 22 S. 4th Ave. Suite 301 659-8333	CASTLE ROCK 355 S. Wilcox 688-5145	ENGLEWOOD 4857 S. Broadway 761-1340
---	--	---	--	---

FORM MUST BE COMPLETED IN FULL

Name of Applicant Robert McNeely Phone 375 9500
841 9409

Mailing Address of Applicant 10204 E Meadow Run
Permit to be Sent to: Parker Co 80134

Name Jane
Address PO BOX 1185, PARKER CO 80134

Street Address & Complete Legal Description of Property for which Permit is being Requested (Attach legal if necessary) 10204 E MEADOW RUN
PARKER, CO. 80134 LOT 138, HIDDEN VILLAGE, FL. 5

PROVIDE MAP OR DIRECTIONS FOR LOCATING PROPERTY ON REVERSE SIDE OF THIS APPLICATION.
Source of Water: Private Well () Public (Specify) _____

Name of Original Home Owner (If Known) _____

Contractor who Installed System (If Known) _____

A non-refundable fee of \$75.00 shall be payable when the application is made. The permit issued as a result of this application shall remain valid until the property is sold or otherwise altered from domestic use or until the sewage disposal system fails to operate in an approved manner.

* * * * *

OWNER/AGENT CERTIFICATION

(I), Naren Sturges as agent Cooper Owner/Agent of the dwelling at the location described in this application do hereby certify that the sewage disposal system has been in continuous use, operating satisfactorily, and without malfunction. The septic tank was pumped TO BE PUMPED (Date). REGULATIONS REQUIRE SEPTIC TANKS BE PUMPED EVERY FOUR (4) YEARS.

DATE 7/23/87 SIGNATURE Naren C Sturges

* * * * *

Inspection Date _____ Approved () Denied ()

Public Health Sanitarian _____

Permit Fee \$ 75.00 Check No. 1130 M.O. _____ Cash _____ Rec'd by AS Date 7-29-87

TRI-COUNTY DISTRICT HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

2691

Adams City
4301 E. 72nd Ave.
288-6816

Brighton
1895 Egbert
659-4000

Englewood
4857 So. Broadway
761-1340

Aurora Office
15400 E. 14th Place
341-9370

Castle Rock
502 3rd St.
688-5145

West Adams City
7475 Dakin
428-8543

10204 E. Meadow Run

APPLICATION FOR PERMIT TO CONSTRUCT, REMODEL, OR INSTALL A WASTE DISPOSAL SYSTEM

Address (Legal Description) Lot 138, Hidden Village, filing #5
Owner Michael B. Parker Address 97 Maximus, Littleton Telephone No. 770-1214
Installed by J.P. excavating Address _____ Telephone No. _____

GENERAL INFORMATION

Type of Waste System: Residence X Commercial _____ Other _____
Size of Lot 2.6 acres
Percolation Rate #1 5.13 #2 6.0 #3 5.93 #4 _____ #5 _____ #6 _____
Average 5.68 minutes per inch. Depth of 1st Ground Water None
Soil Profile 1' to 10' See Attached Percolation Test #77319, AA Engineers & Assoc., Inc.
Source of Domestic Water: Public (name) _____
Private well X Proposed Depth _____ Distance from Sewage System _____
Estimated Daily Sewage Flow 450 x 1.5 = 675 maximum G.P.D.

RESIDENCE

Number of Bedrooms 3 ⁴ Tubs or Showers 3 Toilets 3 Lavatory 3 Sinks 1

COMMERCIAL or Other: Attach estimated daily sewage flow data.
Depth of Building Drain _____

CONSTRUCTION INFORMATION

Septic Tank Capacity 1250 2 compartment gallons Material Standard Concrete
Inlet "1" or Baffle +3" Outlet "1" or Baffle -3"
Soil Absorption System Trench Bed X Pit _____
Required Absorption Area in square feet 800 Filler Material Size 1/2"-1 1/2" Depth 6"
Distribution Line Material PVC perforated Diameter 4" Depth of Field = 3" minimum
5' maximum

or other type disposal system attach complete design and specification data.

Owner or Agent Michael B. Parker Date July 12, 1977

Tri-County District H.D. _____ Date _____


Water Pollution Control Comm. _____ Date _____

Local Building & Zoning _____ Date _____


Public Water & Sewer District _____ Date _____
Permit Issued M.L. Berglund (health officer) 7-13-77 Date _____
Supporting data (attached) _____ Soil Profile _____
Plot Plans _____ Special Design Data _____
Percolation Data _____

The construction of this nonmunicipal waste disposal system will comply with TCDHD Reg. #2/69 and all other applicable laws, ordinances, standards or resolutions. Russell A. Parnes Owner.

System inspected and approved (date) 10-31-77 Sanitarian J. Julian
Permit File No. 2691 Fiscal Control No. 3864



Note:
 Leach field is 30' from the dry gulch



ENGINEERS & ASSOCIATES, INC.

Civil, Surveying, Soil-Rock Mechanics, Structures and Foundations

July 12, 1977

PERCOLATION TEST

#77319

LOCATION: Lot 138, Hidden Village, #5
Douglas County, Colorado

FOR: Mr. M. Parker
97 Maximus
Littleton, CO 80124

TEST DATE: 7/6/77

This is to verify that this office has conducted a percolation test on the proposed absorption field for the above mentioned site. The percolation test was conducted in accordance with the regulations of the Tri-County Health Department. The following are the results of that study:

TEST HOLE	DEPTH	RATE OF PERCOLATION PER INCH DROP	SUBSOIL
1	3'	5.13 minutes	SC, well graded, organic, slightly calcareous, silty, micaceous, dark brown
2	3'	6.0 minutes	SAME AS ABOVE
3	3'	5.93 minutes	SAME AS ABOVE

A ten (10) foot profile boring was drilled immediately adjacent to the proposed absorption field and revealed the following:

0'-3'; SC, well graded, friable, organic structure, slightly calcareous, slightly micaceous, plastic clay fraction, dark brown

3'-5'; SW, micaceous, poorly cemented, slightly calcareous, silty, light brown-tan

5'-10'; ML-SW, lenticular, micaceous, light brown-tan

No free ground water was encountered upon completion of drilling, or for a period of twenty-four (24) hours thereafter.

Faint, illegible text at the top of the page, possibly a header or title.

Faint, illegible text in the middle section of the page.



Faint, illegible text to the right of the circular stamp, possibly a signature or a date.

Page 2
L138, Hidden Village, #5
Mr. M. Parker

The subsoils encountered conform to USDA Soil Survey classification of Peyton-Pring-Crowfoot sandy loams; 5-25 percent slopes; (datum, Soil Survey Castle Rock Area, Colorado, USDA Soil Conservation Service, Colorado Agricultural Experiment Station, November, 1974).

The subject site is located as legally described, facing north onto Meadow Run, which is presently an improved gravel surface roadway. The site comprises 2.6 acres in Section 8, T7S, R65W, 6th P.M., Douglas County. Property to the immediate east and west is presently occupied by residential structures, whereas the sites to the north of Meadow Run and to the south are presently vacant. No existing domestic water wells on either developed site are in conflict with the proposed location of the subject absorption field. Utilities are located above ground on the north side of Meadow Run. The site is traversed on the south by an existing dry wash. Drainage across the site is adequate with an average drop of 7% across undulating terrain to the general south-southeast, ultimately discharging into the aforementioned dry wash.

No adverse geological conditions were observed at the subject site that would disqualify the site for installation of standard septic tank/leaching field type ISDS.

As revealed by the percolation test rates the subsoils are ideal to receive the effluents of a standard septic system. The porous nature of the mixture of sand and clay/silt fines is quite conducive to seepage.


We appreciate the opportunity to be of service to you in this project. Should further clarification or design be required, please consult our offices.

Very truly yours,

AA ENGINEERS & ASSOCIATES, INC.


H. S. Adnan

H.S. Adnan, P.E.



H. W. Topping
H.W. Topping, Soil Dept Director

HSA/ht



LEGEND

- ⊙¹ TEST HOLE & No
- PROPERTY CORNER (IDENTIFIED)
- ↙^D DRAINAGE SLOPE
- PROPERTY LINE
- ⌊ ASSUMED BUILDING LOCATION
- ASSUMED PR. LINE
- ☑ PER PLOT PLAN

TEST HOLE LOCATION PLAN



LOT 138, HIDDEN VILLAGE, FILING #5

SCALE: 1" = 100'

FIG 1

ASSUMED ELEVATION 100.00
SEE TEST-HOLE PLAN

ELEVATION IN FEET



SOIL GROUP SYMBOLS
UNIFIED SOIL CLASSIFICATION SYSTEM

- SOD, HUMUS, TOPSOIL
- GW WELL GRADED GRAVELS
- GP POORLY GRADED GRAVELS
- GM GRAVEL-SAND-SILT
- GC GRAVEL-SAND-CLAY
- SW WELL GRADED SAND
- SP POORLY GRADED SAND
- SM SAND-SILT INTERMIXED
- SC SAND-CLAY INTERMIXED
- ML INORGANIC SILTS
- MH ELASTIC SILTS
- CL CLAY-LOW-MED. PLASTICITY-LEAN
- CH CLAY-HIGH PLASTICITY-FAT
- OH ORGANIC CLAY MED-HIGH PLASTIC
- CONGLOMERATE
- SHALE
- CLAYSTONE
- SILTSTONE
- SANDSTONE
- UNCLASSIFIED ROCKS
- PEAT
- FILL

GENERAL NOTES

- GROUND WATER ON DATE OF DRILLING
- PENETRATION TEST INDICATIVE OF RELATIVE STIFFNESS: BLOW/FT 140# HAMMER DROPPED 30 INCHES
- MC MOISTURE CONTENT %
- QU UNCONFINED COMPRESSIVE STRENGTH IN P.S.F.

LOGS OF EXPLORATORY HOLES

LOCATION LOT 138 HIDDEN VILLAGE 5

SUBSURFACE INVESTIGATION
CONDUCTED ON 7/6/77

FIG. 2